


Valve bar assembly kit

275408



Notice

Failure to torque the hex head capscrews (P/N 275045) to the specified torque may result in damage to your equipment and void the warranty of the product.

Version	01
Date of issue	May 2012
Form	404429
Section	K1
Page	30

© SKF is a registered trademark of the SKF Group.

© Lincoln is a registered trademark of Lincoln Industrial Corp.

© SKF Group 2012

The contents of this publication are the copyright of the publisher and may not be reproduced (even extracts) unless prior written permission is granted. Every care has been taken to ensure the accuracy of the information contained in this publication but no liability can be accepted for any loss or damage whether direct, indirect or consequential arising out of the use of the information contained herein.

SKF PUB LS/11 12904 EN.US · MAY 2012 · FORM 404429

Printed in USA on environmentally friendly paper.

